

RHODE ISLAND T.F. GREEN INTERNATIONAL AIRPORT (PVD)

FIELD CONDITION REPORT

OFFICE: (401) 691-2265 24 HR: (401) 447-6893

DATE: 4/25/2024

TIME: 0:45

INSPECTED BY: PETER TERRERI

UPDATED BY: PETER TERRERI

WEATHER RELATED UPDATES

SURFACE CONDITIONS

ALL SURFACES DRY

BRAKING ACTION / RwyCC VALUES

RUNWAY TIME TOUCHDOWN MIDPOINT ROLLOUT

TAXIWAY AND APRON BRAKING ACTION : TAXIWAYS: APRONS:

AIRFIELD REMARKS

<u>SURFACES</u>	<u>STATUS</u>	<u>REMARKS</u>
RUNWAY 5-23		CENTERLINE MARKINGS OBSCURED
RUNWAY 16-34		RUNWAY 16: PAPI OUT OF SERVICE CENTERLINE MARKINGS OBSCURED
TAXIWAY A		
TAXIWAY B		
TAXIWAY C	CLOSED	BETWEEN TAXIWAY C1 AND RUNWAY 34 WORK IN PROGRESS CONSTRUCTION SURFACE PAINTED HOLDING POSITION SIGNS AT RUNWAY 5-23, SW SIDE, NON STANDARD
TAXIWAY C1		
TAXIWAY E		
TAXIWAY F		
TAXIWAY M		
TAXIWAY M1		
TAXIWAY M2		
TAXIWAY N		EDGE MARKINGS BETWEEN RUNWAY 5-23 AND TAXIWAY M REMOVED
TAXIWAY S		
TAXIWAY T		LOCATION / TAXIWAY E DIRECTION SIGN UNLIT RUN UP PAD CLOSED
TAXIWAY V	CLOSED	BETWEEN TAXIWAY T AND RUNWAY 16 AVAILABLE FOR CROSSING AT TAXIWAY C
NORTHEAST RAMP		
NORTHWEST RAMP		
TERMINAL RAMP		

MISCELLANEOUS AERODROME REMARKS

OBSTRUCTION: SOUND BARRIER (0.54NM SW PVD) 75FT MSL (13FT AGL) OBSTRUCTION LIGHTS UNLIT AND
REMOVED